

VEHICLE INSPECTION REPORT

YF19UVK

MERCEDES-BENZ ATEGO 1321

Non Runner
Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Location	Doncaster	Colour	SILVER	Gearbox	AUTOMATIC
Reg. date	10/07/2019	VIN	WDB96702620363577	Axle Combi	4x2
Year	2019	Body Style	Curtainside	Rear Suspension	Air
Mileage	579,282 Km Not Warranted	Service history	None	Rear Doors	Roller
Fuel Type	DIESEL	MOT Due	31/08/2026	Tail Lift	Tuckaway
GVW	13500kg	Cab Type	LOW ROOF SLEEPER CAB		

NON-RUNNER DOES NOT TURN OVER

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Digital radio