

VEHICLE INSPECTION REPORT

WX12BSZ

Ford Fiesta 1.4 TDCi 70

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Avonmouth	GVW	1535kg	CAP Clean	£570.00
Reg. date	02/08/2012	Colour	WHITE	CAP Average	£450.00
Year	2012	VIN	WF0RXXGAJRCD27305	CAP Below	£300.00
Mileage	133,426 Miles Warranted	Body Style	Panel Van SWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	23/02/2027	Gears	5

E/MIRRORS, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- USB/iPod interface
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Radio/CD
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing nsf
Chipped
1 To 5



5: A Post ns
Rusted
Over 5mm

6: Door nsf
Chipped
Multiple Chips



7: Sill ns
Rusted
Over 5mm

8: Sill ns
Dented
Over 30mm




9: Qtr Panel nsr
Chipped
Multiple Chips

10: Bumper Rear
Insecure
Action Required



11: Bumper Rear
Scratched
Over 100mm Thru Paint

12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Bumper Rear Moulding
Broken
Replace

14: Qtr Panel osr
Chipped
Over 5mm



15: Qtr Panel osr
Dented
Over 30mm

16: Qtr Panel osr
Poor Previous Repair
Poor Paint




17: Door osf
Chipped
Multiple Chips

18: Door osf
Rusted
Over 5mm



19: Door osf
Chipped
Multiple Chips

20: Sill os
Dented
Over 30mm





21: Wing osf
Rusted
Over 5mm

22: Bumper Front
Scratched
Over 25mm Not Thru Paint



23: Bumper Front
Scratched
Over 100mm Thru Paint

24: Seat Back Cover osf
Torn
Over 3mm



25: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
ABS light illuminated		OK	DPF light illuminated		OK