

VEHICLE INSPECTION REPORT

CP16RZL

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	3500kg	CAP Clean	£4,125.00
Reg. date	03/08/2016	Colour	WHITE	CAP Average	£3,375.00
Year	2016	VIN	WF0XXXTTGXGA14217	CAP Below	£2,425.00
Mileage	63,394 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	08/07/2027	Gears	6

V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES, SIDE LOADING DOOR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
UpTo 25mm Thru Paint

4: Qtr Panel Trim ns
Missing
Replace



5: Door nsr
Dented
Over 30mm

6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel osr
Dented
With Paint Damage



9: Qtr Panel Moulding os
Broken
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK