

VEHICLE INSPECTION REPORT

HX24WSD

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Livingston	GVW	7490kg	Gearbox	AUTOMATIC
Reg. date	08/05/2024	Colour	WHITE	Axle Combi	4x2
Year	2024	VIN	W1T96700820669863	Rear Suspension	Steel
Mileage	890 Km Warranted	Body Style	Pole Carrier		
Fuel Type	DIESEL	Cab Type	DAY CAB		

X-HIDOU 062/B2 REMOTE CRANE (YEAR 2023), WEIGH SYSTEM, REAR VIEW CAMERA, SURROUND CAMERA SYSTEM.

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
Airbag light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK