

VEHICLE INSPECTION REPORT

HX24WSV

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Livingston

GVW 7490kg

Gearbox AUTOMATIC

Reg. date 08/05/2024

Colour WHITE

Axle Combi 4x2

Year 2024

VIN W1T96700120666481

Rear Suspension Steel

Mileage 704 Km Warranted

Body Style Pole Carrier

Fuel Type DIESEL

Cab Type DAY CAB

X-HIDOU 062/B2 REMOTE CRANE (YEAR 2023), WEIGH SYSTEM, REAR VIEW CAMERA, SURROUND CAMERA SYSTEM.

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
Airbag light illuminated	OK		Oil warning light illuminated	OK	
ABS light illuminated	OK		DPF light illuminated	OK	
			Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	