

VEHICLE INSPECTION REPORT

CN68DPX

Citroen Berlingo 625 1.6 BLUEHDI ENTERPRISE 75PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	VIN	VF77BBHW6JN538568	MOT Due	05/01/2027
Reg. date	21/09/2018	Body Style	Panel Van SWB	CAP Clean	£3,200.00
Year	2018	Service history	Part	CAP Average	£2,725.00
Mileage	73,183 Miles Warranted	Service documents	Service Book	CAP Below	£2,075.00
Fuel Type	DIESEL	Number of stamps	5	Gearbox	MANUAL
GVM	1960kg	Last service date	02/01/2025	Gears	5
Colour	WHITE	Last service miles	62,636		

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Number Plate Front
Broken
Replace



3: Wing nsf
Dented
With Paint Damage

4: Door nsf
Dented
With Paint Damage




5: Qtr Panel nsr
Chipped
Multiple Chips

6: Door nsr
Dented
Over 30mm



7: Door nsr
Dented
With Paint Damage

8: Qtr Panel osr
Dented
Over 30mm



9: Seat Base Cover of
Burn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		