

VEHICLE INSPECTION REPORT

FL69XLR

Vauxhall Vivaro 2900 1.5d 100PS Edition

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	44124
		Cap Code	VAVI15191DVDTM2 3 L

Details

Location	Doncaster	GVW	2830kg	CAP Clean	£6,650.00
Reg. date	31/12/2019	Colour	WHITE	CAP Average	£5,725.00
Year	2019	VIN	VXEVBVHRKL7007097	CAP Below	£4,475.00
Mileage	61,909 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	24/06/2027	Gears	6

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Seat Base Cover osf
Torn
Over 3mm



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		