

# VEHICLE INSPECTION REPORT

**LX67OCW**

## IVECO EUROCARGO 180-250

### Inspection

### Vehicle

|     |                |
|-----|----------------|
| VAT | Plus VAT       |
| V5  | Buyer To Apply |

### Details

|           |                          |            |                   |                 |        |
|-----------|--------------------------|------------|-------------------|-----------------|--------|
| Location  | Bedford                  | GVW        | 18000kg           | Gearbox         | MANUAL |
| Reg. date | 15/01/2018               | Colour     | WHITE             | Axle Combi      | 4x2    |
| Year      | 2018                     | VIN        | ZCFA71TJ202667935 | Rear Suspension | Steel  |
| Mileage   | 152,047 Km Not Warranted | Body Style | Dropside          |                 |        |
| Fuel Type | DIESEL                   | Cab Type   | DAY CAB           |                 |        |

\*WARNING LIGHTS ON DASH\* SURROUND CAMERA SYSTEM

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features

- Park assist camera
- Air conditioning