

VEHICLE INSPECTION REPORT

AF23PMY

Ford Transit 320 2.0 EcoBlue 170ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 05/05/2023

Year 2023

Mileage 26,741 Miles
Warranted

Fuel Type DIESEL

GVW 3200kg

Colour BLACK

VIN WF0ZXXTTGZPC32930

Body Style Panel Van L2

Service history None

MOT Due 21/05/2027

CAP Clean £23,100.00

CAP Average £21,350.00

CAP Below £18,350.00

Gearbox AUTOMATIC

Gears 6

TWIN SIDE LOAD DOORS, E/MIRRORS, AD-BLUE, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF

OSR



Spare


Features

- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Auxiliary input socket
- Drivers airbag
- Heated front seat
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Over 5mm

4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint

6: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



7: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint

8: Seat Base Cover osf
Soiled
Heavy



9: Seat Back Cover osf
Soiled
Heavy

10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK