

VEHICLE INSPECTION REPORT

SK17VNE

Scania S 580

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 23/05/2017

Year 2017

Mileage 907,120 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN YS2S6X20002134455

Body Style Tractor Unit

Service history None

MOT Due 30/11/2026

Cab Type HIGHLINE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

SINGLE LINE PTO HYDRAULIC, TOP LIGHT BAR, REAR-LIFT, SLIDING 5TH WHEEL

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Digital radio
- Leather seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Rusted
Over 5mm



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front Moulding
Broken
Replace

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Bumper Front Moulding
Broken
Replace

6: Door Mirror Assy nsf
Broken
Replace



7: Qtr Panel Trim ns
Scuffed
Over 25mm

8: Qtr Panel Moulding os
Broken
Replace



9: Screen Front
Chipped
Over 10mm

10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		