

## VEHICLE INSPECTION REPORT

**YO190UJ**

### Ford Transit Connect 240 BASE 1.5 ECOBLUE 100PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Buyer To Apply

#### Details

Reg. date 07/05/2019

Year 2019

Mileage 161,477 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSKD62090

Body Style Panel Van L2

MOT Due Expired

CAP Clean £3,550.00

CAP Average £3,075.00

CAP Below £2,475.00

Gearbox MANUAL

Gears 6

\*ONLY RUNS WITH JUMP PACK ATTACHED, DASH DOES NOT DISPLAY\* AD BLUE, SIDE LOADING DOOR

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Chipped  
Multiple Chips



2: Bonnet  
Chipped  
Multiple Chips



3: Screen Front  
Chipped  
UpTo 10mm



4: Bumper Front  
Cracked  
Over 25mm



5: Grille Front  
Broken  
Replace



6: Panel Front  
Chipped  
Multiple Chips



7: General Exterior  
Soiled  
Light



8: Wing nsf  
Chipped  
Multiple Chips



9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Door nsr  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



12: General Exterior  
Soiled  
Light



13: Door nsr  
Dented  
Over 30mm



14: Door osf  
Scratched  
Over 25mm Thru Paint





15: Carpets Front  
Holed  
Over 3mm

Interior

Carpets Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	Fault		