

VEHICLE INSPECTION REPORT

FE21YPN

Vauxhall Vivaro 3100 2.0 120PS EDITION

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	3100kg	CAP Clean	£8,125.00
Reg. date	06/04/2021	Colour	WHITE	CAP Average	£7,275.00
Year	2021	VIN	VXEVFAHKKM7815680	CAP Below	£5,975.00
Mileage	52,095 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	18/12/2026	Gears	6

WARNING LIGHT ON DASH AD BLUE, RACKING IN REAR, TWIN SIDE LOADING DOORS, E/MIRRORS, INVERTER

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag


Photos








Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Not Thru Paint



2: Qtr Panel osr
Scratched
Over 25mm Thru Paint



3: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

4: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
Airbag light illuminated		Fault			
ABS light illuminated		OK			