

VEHICLE INSPECTION REPORT

FE21YOO

Vauxhall Vivaro 3100 2.0 120PS EDITION

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	3100kg	CAP Clean	£8,925.00
Reg. date	06/04/2021	Colour	WHITE	CAP Average	£7,975.00
Year	2021	VIN	VXEVFAHKKM7816371	CAP Below	£6,550.00
Mileage	38,804 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	11/02/2027	Gears	6

AD BLUE, TWIN SIDE LOADING DOORS, RACKING IN REAR, INVERTER, E/MIRRORS, ROOF RACK

Tyres

NSF

NSR

OSF

OSR





Spare

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Dented
With Paint Damage



3: Door nsf
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel osr
Rusted
Over 5mm

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Door Moulding osf
Missing
Replace

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		