

# VEHICLE INSPECTION REPORT

**LRP216M**

## VOLVO F89

Imported  
Inspection

| Vehicle |           |
|---------|-----------|
| VAT     | Margin    |
| V5      | To Follow |

### Details

|           |                            |            |               |            |             |
|-----------|----------------------------|------------|---------------|------------|-------------|
| Location  | Onsite Customer Auction    | Fuel Type  | DIESEL        | Cab Type   | SLEEPER CAB |
| Reg. date | 01/09/2024                 | Colour     | GREEN         | Gearbox    | Manual      |
| Year      | 1974                       | VIN        | F89466X211025 | Axle Combi | 6x2         |
| Mileage   | 74,239 Miles Not Warranted | Body Style | Tractor Unit  |            |             |

Twin Wheel Tag Axle

|       |
|-------|
| Tyres |
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |