



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BD69LWZ

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 13/11/2019

Year 2019

Mileage 104,731 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTREKS21986

Body Style Panel Van L2

MOT Due 12/11/2025

CAP Clean £5,075.00

CAP Average £4,475.00

CAP Below £3,575.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Front electric windows

Photos



Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Fuel Flap
Missing
Replace



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
2 Or Less Up To 10mm



8: Qtr Panel nsr
Dented
Over 2 Up To 10mm



9: Other
N/A
N/A



10: Qtr Panel nsr
Dented
Over 30mm



11: Qtr Panel nsr
Dented
Over 30mm



12: Lamp nsr
Broken
Replace



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



16: Seat Base Cover osf
Torn
Over 3mm



17: Other
N/A
N/A



18: Seat Base Cover nsf
Burn
Over 3mm



19: Seat Base Cover nsf
Burn
Over 3mm



20: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK