

VEHICLE INSPECTION REPORT

WT25PPU

Nissan Interstar F35 2.0 DCI 150ps Acenta

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£20,150.00
Reg. date	31/07/2025	Colour	WHITE	CAP Average	£19,400.00
Year	2025	VIN	VNVNGA00474471928	CAP Below	£17,450.00
Mileage	20,096 Miles Not Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	30/07/2028	Gears	6

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Wing nsf
Scratched
Over 25mm Thru Paint



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: C Post ns
Dented
With Paint Damage

12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Door osr
Dented
With Paint Damage

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		