

VEHICLE INSPECTION REPORT

FP67SLZ

DAF LF 210

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Bedford	Colour	WHITE	Axle Combi	4x2
Reg. date	24/02/2018	VIN	XLRAEL1500L468773	Rear Suspension	Steel
Year	2018	Body Style	Curtainside	Rear Doors	Barn </td
Mileage	209,615 Km Not Warranted	MOT Due	30/09/2026	Tail Lift	Tuckaway
Fuel Type	DIESEL	Cab Type	DAY CAB		
GVW	12000kg	Gearbox	AUTOMATIC		

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



