

VEHICLE INSPECTION REPORT

FX13CTE

SHIBAURA CM374

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	Mileage	TBC	VIN	10353
Reg. date	01/03/2013	Fuel Type	Diesel	Body Style	Ride on Mower
Year	2013	Colour	RED	Gearbox	Hydrostatic

Vehicle Recorded As DVLA SCRAPPED MARKER On Condition Alert Register. MUTHING MUFM160 MOWER DECK (YEAR 2013) S/N 3117305

Tyres

NSF
NSR
OSF
OSR
Spare