

VEHICLE INSPECTION REPORT

YP67ZZS

Ford Transit Courier 1.5 TDCI 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	20/11/2017	VIN	WF0WXXTACWHC41787	CAP Below	£1,875.00
Year	2017	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	122,713 Miles Warranted	MOT Due	02/12/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£2,900.00		
Colour	WHITE	CAP Average	£2,475.00		

SINGLE SIDE DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: General Exterior
Soiled
Light



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Not Thru Paint



5: Qtr Panel osr
Chipped
Multiple Chips



6: Door osf
Scratched
Over 25mm Thru Paint



7: General Exterior
Soiled
Light



8: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK