

# VEHICLE INSPECTION REPORT

**YR18JFZ**

## Ford Transit Connect 220 1.5 TDCI 100PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date 28/03/2018

Year 2018

Mileage 65,633 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRHD64788

Body Style Panel Van L1

MOT Due 27/03/2026

CAP Clean £4,075.00

CAP Average £3,525.00

CAP Below £2,725.00

Gearbox MANUAL

Gears 5

SINGLE SIDE DOOR

### Tyres

NSF

NSR

OSF


OSR


Spare

## Features

- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Chipped  
Multiple Chips



2: Bonnet  
Chipped  
Multiple Chips



3: Screen Front  
Chipped  
UpTo 10mm



4: Wing nsf  
Chipped  
Multiple Chips



5: Door nsr  
Chipped  
Multiple Chips



6: Reflector osr  
Broken  
Replace



7: Bumper Rear  
Scratched  
Up To 25mm Not Thru Paint



8: Qtr Panel osr  
Dented  
Over 30mm



9: Seat Base Cover osf  
Burn  
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK