

VEHICLE INSPECTION REPORT

PE17HNT

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	VIN	XLRTGM4100G149351	Cab Type	SLEEPER CAB
Reg. date	06/03/2017	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Year	2017	Service history	Full	Axle Combi	6x2
Mileage	1,261,097 Km Warranted	Service documents	Printout	Steering Combi	Mid-Lift
Fuel Type	DIESEL	Last service date	13/08/2025	Rear Suspension	Air
GVW	44000kg	Last service miles	119,416		
Colour	RED	MOT Due	31/03/2027		

COLLECTED AS NON-RUNNER - AIR LEAK, WILL NOT BUILD UP AIR, WANRING LIGHTS ON DASH


Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Number Plate Front
Broken
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel nsr
Rusted
Over 5mm

6: Door osf
Dented
With Paint Damage



7: Screen Front
Cracked
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		