

VEHICLE INSPECTION REPORT

YR18JGU

Ford Transit Connect 1.5 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date 28/03/2018

Year 2018

Mileage 105,993 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRHD64776

Body Style Panel Van L1

MOT Due 08/02/2026

CAP Clean £3,275.00

CAP Average £2,850.00

CAP Below £2,200.00

Gearbox MANUAL

Gears 5

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Grille Front
Broken
Replace



3: Bonnet
Chipped
Multiple Chips



4: Wing nsf
Chipped
Over 5mm



5: Wing nsf
Dented
With Paint Damage



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Chipped
Over 5mm




8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Chipped
Over 5mm

10: Door nsr
Dented
Over 30mm



11: Door osf
Chipped
Edge Chip

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK