

VEHICLE INSPECTION REPORT

008429

SEB CAPSTAN DIESEL WINCH

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Mileage	Not Showing	VIN	8429
Reg. date		Fuel Type			
Year	1991	Colour			

SINGLE AXLE TRAILER

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



