

VEHICLE INSPECTION REPORT

LX66GWK

Citroen Relay 35 Hdi 35 2.2 HDI 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Code	999900

Details

Location	Doncaster	Fuel Type	DIESEL	Body Style	EXHIBITION UNIT
Reg. date	01/09/2016	GVW	3500kg	MOT Due	14/05/2027
Year	2016	Colour	WHITE	Gearbox	MANUAL
Mileage	25,884 Miles Warranted	VIN	VF7YCTMAU12978700		

Tyres






NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Fuel Flap
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		