

VEHICLE INSPECTION REPORT

LX66GUH

CITROEN RELAY 35 HDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Avonmouth

Reg. date 01/09/2016

Year 2016

Mileage 25,365 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN VF7YCTMAU12981543

Body Style Exhibition Unit

MOT Due 19/04/2027

Gearbox MANUAL

AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR





Spare



Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking

Photos










Condition Check




Damage Photos



1: Door Mirror Assy nsf
Broken
Replace



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Fuel Flap
Chipped
Over 5mm



4: Wheel nsr
Scratched
Over 50mm



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Wing osf
Chipped
Over 5mm



10: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				
Windows	OK		Radio	OK	