

VEHICLE INSPECTION REPORT

LX67DAO

CITROEN RELAY 35 2.0 BLUEHDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Code	999900

Details

Location	Avonmouth	Fuel Type	DIESEL	MOT Due	21/07/2027
Reg. date	01/10/2017	Colour	WHITE	Gearbox	MANUAL
Year	2017	VIN	VF7YC2MAU12E30096		
Mileage	7,743 Miles Warranted	Body Style	Exhibition Unit		

AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR





Spare




Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking

Photos










Condition Check




Damage Photos



1: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Fuel Flap
Chipped
Over 5mm



4: Qtr Panel nsr
Hole
Over 10mm



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Sill ns
Dented
Over 30mm



7: Sill os
Dented
Over 30mm



8: Door osf
Chipped
Over 5mm



9: Bonnet
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK						
				Radio	OK		