

VEHICLE INSPECTION REPORT

HX73YPA

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location	Livingston	GVW	7490kg	Cab Type	DAY CAB
Reg. date	19/10/2023	Colour	WHITE	Gearbox	AUTOMATIC
Year	2023	VIN	W1T96700620678884	Axle Combi	4x2
Mileage	20,718 Km Warranted	Body Style	Pole Carrier	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/10/2026		

WARNING LIGHT ON DASH PALFINGER PK 5.501 REMOTE CRANE (YEAR 2023), REAR VIEW CAMERA.


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm



2: Door of
Dented
Over 2 Up To 10mm



3: Bumper Front Moulding
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Roof / sunroof	OK			Radio	OK		
Windows	OK			Steering	OK		