

VEHICLE INSPECTION REPORT

HX73YPC

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location	Livingston	Colour	WHITE	Cab Type	DAY CAB
Reg. date	19/10/2023	VIN	W1T96700620673913	Gearbox	AUTOMATIC
Year	2023	Body Style	Pole Carrier	Axle Combi	4x2
Mileage	19,761 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout		
GVW	7490kg	MOT Due	31/10/2026		

PALFINGER PK 5.501 REMOTE CRANE (YEAR 2023), WEIGH SYSTEM, REAR VIEW CAMERA.


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm

2: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK