

VEHICLE INSPECTION REPORT

DN68EBD

Daf XF 480

Non Runner
Inspection

Vehicle	
Serious Damage?	No
VAT	Plus VAT
V5	Present

Details

Location	Bedford	GVW	44000kg	Gearbox	AUTOMATIC
Reg. date	02/11/2018	Colour	WHITE	Axle Combi	6x2
Year	2018	VIN	XLRTGH4300G234506	Steering Combi	Mid-Lift
Mileage	Not Showing	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	Cab Type	SUPER SPACE CAB		


NON RUNNER-DOES NOT POWER UP, GEARBOX REMOVED SLIDING 5TH WHEEL, MOT SHOWS 678,644KM 06/08/2025









Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door osf
Chipped
Edge Chip

6: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
-

Engine Runs Fault