

VEHICLE INSPECTION REPORT

KU18EHT

MERCEDES-BENZ ACTROS 2532

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Doncaster	GVW	26000kg	Gearbox	AUTOMATIC
Reg. date	18/04/2018	Colour	WHITE	Axle Combi	6x2
Year	2018	VIN	WDB96302020235915	Rear Suspension	Air
Mileage	584,028 Km Not Warranted	Body Style	Curtainside	Rear Doors	Barn
Fuel Type	DIESEL	Cab Type	SLEEPER CAB		

WARNING LIGHTS ON DASH, NO POWER TO TAIL LIFT REAR LIFT

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Digital radio
- Air conditioning

Photos





