

VEHICLE INSPECTION REPORT

BF70NNR

Iveco Daily 35-120

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow
Cap Code IVDA23S352VDTM2 4
L

Details

Location	Doncaster	Fuel Type	DIESEL	Body Style	Panel Van
Reg. date	05/02/2021	GVW	3500kg	MOT Due	01/04/2027
Year	2021	Colour	WHITE	Gearbox	MANUAL
Mileage	92,381 Miles Warranted	VIN	ZCFC3358505385068	Gears	6

COLLECTED AS NON RUNNER - VENDOR STATESLIMP MODE, WARNING LIGHTS ON DASH 3520 WB, E/MIRRORS, AD-BLUE, RACKING

Tyres

NSF

NSR

OSF

OSR





Spare



Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Front parking sensor
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
Dented
Over 30mm

4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

8: Seat Base Cover osf
Torn
Over 3mm



9: Seat Base Cover nsf
Soiled
Heavy

10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	Fault	
ABS light illuminated	OK				