

VEHICLE INSPECTION REPORT

LT19AMX

ISUZU N75 150

Cat: N
Inspection

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Code	999900

Details

Location	Bedford	GVW	7500kg	Cab Type	DAY CAB
Reg. date	01/04/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	JAANPR85HJ7100423	Axle Combi	4x2
Mileage	146,222 Km Warranted	Body Style	Refuse Collector	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/05/2027		

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair.

WARNING LIGHT ON DASH SINGLE TERBERG LIFT

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Air conditioning

Photos





