

VEHICLE INSPECTION REPORT

BG23GZK

Land Rover Range Rover Sport 3.0 P440E DYNAMIC SE PHEV

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	Present
Cap Id	100116
Cap Code	LRRS30DYE5EXTA4 4

nama
GRADE
3

Details

Location	Avonmouth	Colour	GREEN	CAP Below	£51,600.00
Reg. date	28/03/2023	VIN	SAL1A2A40PA127360	Gearbox	AUTOMATIC
Year	2023	Body Style	SUV	Gears	8
Mileage	14,635 Miles Not Warranted	MOT Due	Expired	Doors	5
Fuel Type	PETROL-PHEV	CAP Clean	£55,500.00	Axle Combi	4x4
GVW	3450kg	CAP Average	£53,600.00		

KEYLESS IGNITION, E/MIRRORS, PLUG IN, CABLES IN BOOT

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Cruise control
- Park assist camera
- Trip computer
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Traction control
- Immobiliser
- Front parking sensor
- Rear parking sensor
- Digital radio
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Drivers airbag
- Tyre pressure monitor
- Remote central locking
- Heated front seat
- Reverse parking aid
- Mobile phone App interface
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Passenger airbag
- Alarm
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- USB/iPod interface
- Air conditioning
- Front armrest
- Rear electric windows
- Side airbags
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint

4: Bumper Rear
Scratched
Up To 25mm Thru Paint



5: Tailgate
Scratched
UpTo 25mm Thru Paint

6: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Door Mirror Assy osf
Broken
Replace

8: Bonnet
Chipped
Multiple Chips



9: Door Pad nsr
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK