

VEHICLE INSPECTION REPORT

RK21JXL

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Avonmouth

Reg. date 15/06/2021

Year 2021

Mileage 245,658 Km Not Warranted

Fuel Type DIESEL

GVW 32000kg

Colour WHITE/BLACK

VIN XLRADM4100G345920

Body Style Tipper

MOT Due 31/07/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WARNING LIGHT ON DASH KELBERG STEEL BODY, PALFINGER EPSILON M125L CLASSIC (YEAR 2021), SHEETING SYSTEM, SURROUND CAMERA SYSTEM

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4

Features

- Bluetooth connection
- Radio/CD Multichanger
- Front electric windows
- Cruise control
- USB/iPod interface
- Central locking
- Park assist camera
- Manual sunroof
- Cloth seat trim
- Auxiliary input socket
- Air conditioning


Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm



3: Bumper Front
Dented
With Paint Damage



4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsf
Scratched
UpTo 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Panel Rear
Dented
Hail - Severe



9: Door osf
Dented
With Paint Damage



10: Door osf
Chipped
1 To 5



11: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
Brakes	OK				
Parking Brake	OK				
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				