

# VEHICLE INSPECTION REPORT

**SF19NFL**

## KUBOTA L2421

### Inspection

### Vehicle

|          |          |
|----------|----------|
| VAT      | Plus VAT |
| V5       | Present  |
| Cap Code | 999900   |

### Details

|           |                           |            |                   |            |             |
|-----------|---------------------------|------------|-------------------|------------|-------------|
| Location  | Doncaster                 | Fuel Type  | DIESEL            | Gearbox    | HYDROSTATIC |
| Reg. date | 03/04/2019                | Colour     | ORANGE            | Axle Combi | 4WD         |
| Year      | 2019                      | VIN        | KBTLCBDCTJ8030225 |            |             |
| Mileage   | 3,922 Hours Not Warranted | Body Style | Tractor 4wd       |            |             |

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos



