

VEHICLE INSPECTION REPORT

RK21NRE

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 31/03/2021

Year 2021

Mileage 53,141 Km Warranted

Fuel Type DIESEL

GVW 15000kg

Colour WHITE

VIN XLRAEL2700L500499

Body Style Sweeper

MOT Due 31/01/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

BUCHER BODY, 2494 TOTAL RUNNING HOURS, 1259 SWEEPING HOURS

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4




OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



5: Bumper Rear
Rusted
Over 5mm

6: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



7: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

8: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	