

VEHICLE INSPECTION REPORT

RK21NRZ

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 31/03/2021

Year 2021

Mileage 66,933 Km Warranted

Fuel Type DIESEL

GVW 15000kg

Colour WHITE

VIN XLRAEL2700L500500

Body Style Sweeper

Keys 2

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

BUCHER BODY, 2664 TOTAL RUNNING HOURS, 1287 SWEEPING HOURS

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4



Spare NSO1 NSO2 NSO3 NSO4




OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front
Dented
Over 30mm

2: Fog Lamp Surround os
Missing
Replace



3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Wing nsf
Cracked
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Bumper Rear
Rusted
Over 5mm

8: Wing Front Arch Extension os
Broken
Replace



9: Seat Base Cover nsf
 Holed
 Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK