

VEHICLE INSPECTION REPORT

DE21XKZ

Man TGL 12.220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Cap Code 999900

Details

Location Doncaster

Reg. date 18/05/2021

Year 2021

Mileage 518,553 Km Warranted

Fuel Type Diesel

GVW 12000kg

Colour YELLOW

VIN WMA14DZZ1MY428834

Body Style Recovery

MOT Due 30/09/2027

Cab Type CREW CAB

Gearbox Automatic

Axle Combi 4x2

Rear Suspension Steel

BONIFACE STVLA+SCL DEMOUNT SLIDE BODY (YEAR 2021), SPEC LIFT, SLIDING WINCH, DYNA CYCLE, 3 POINT SEATBELTS, UNDERSEAT STORAGE, REAR VIEW CAMERA

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated

OK

DPF light illuminated

OK

ABS light illuminated

OK