

VEHICLE INSPECTION REPORT

HX15OSJ

MERCEDES-BENZ ANTOS

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Location	Bedford	GVW	18000kg	Gearbox	AUTOMATIC
Reg. date	22/06/2015	Colour	WHITE	Axle Combi	4x2
Year	2015	VIN	WDB9630032L926718	Rear Suspension	Air
Mileage	385,286 Km Warranted	Body Style	Chassis Cab		
Fuel Type	DIESEL	Cab Type	DAY CAB		

WARNING LIGHT ON DASH

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



