

## VEHICLE INSPECTION REPORT

**BKS012**

### Club Car Electric Golf Buggy \*For Spares or Repair, Been Sat For A Few Years, Running When Put In, Believed to be Batteries\*, C/W Charger S/N: AQ0251-236622

|            |                         |           |             |
|------------|-------------------------|-----------|-------------|
| Inspection |                         | Vehicle   |             |
|            |                         | VAT       | Margin      |
|            |                         | V5        | N/A         |
| Details    |                         |           |             |
| Location   | Onsite Customer Auction | Mileage   | Not Showing |
| Reg. date  |                         | Fuel Type |             |
| Year       |                         | Colour    |             |
| Tyres      |                         |           |             |
| NSF        |                         |           |             |
| NSR        |                         |           |             |
| OSF        |                         |           |             |
| OSR        |                         |           |             |
| Spare      |                         |           |             |

### Photos



