

# VEHICLE INSPECTION REPORT

**LL190EN**

## Isuzu N 75.190

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	10/05/2019	VIN	JAANPR75KH7109825	Rear Suspension	Steel
Year	2019	Body Style	Fridge Box	Rear Doors	Barn
Mileage	275,391 Km Warranted	MOT Due	31/07/2025	Tail Lift	Tuckaway
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

GAH UNIT, STANDBY PLUG, SINGLE EVAP, SEPARATOR, SIDE LOAD DOOR

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Qtr Panel nsr  
Cracked  
Replace





3: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint



4: Qtr Panel osr  
 Scratched  
 Over 25mm Thru Paint



5: Qtr Panel osr  
 Cracked  
 Replace

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		