

VEHICLE INSPECTION REPORT

EJ19VZM

DAF LF 260

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Location	Bedford	GVW	18000kg	Gearbox	MANUAL
Reg. date	07/05/2019	Colour	BLACK	Axle Combi	4x2
Year	2019	VIN	XLRAEL3700L482493	Rear Suspension	Steel
Mileage	424,559 Km Warranted	Body Style	Skiploader		
Fuel Type	DIESEL	Cab Type	DAY CAB		

HYVALIFT GEAR, SURROUND CAMERA SYSTEM, SHEETING SYSTEM

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Navigation system
- Park assist camera
- Air conditioning

Photos



