

VEHICLE INSPECTION REPORT

C338766

DON BUR Box DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster	Colour	RED	Axle Combi	Tri
Reg. date	01/01/2013	VIN	SEPBV38GHDL060738	Rear Suspension	Air
Year	2013	Body Style	Trailer	Rear Doors	Roller
Mileage	Not Showing	MOT Due	31/05/2027		
Fuel Type		Brakes	Disc		

BPW AXLES, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare