

VEHICLE INSPECTION REPORT

MX13LMM

MERCEDES ATEGO 1823

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	Colour	WHITE	Axle Combi	4x2
Reg. date	25/07/2013	VIN	WDB9505382L775680	Rear Suspension	Air
Year	2013	Body Style	Curtainside	Rear Doors	Roller
Mileage	370,486 Km Not Warranted	MOT Due	31/05/2027	Tail Lift	Column
Fuel Type	DIESEL	Cab Type	DAY CAB		
GVW	18000kg	Gearbox	AUTOMATIC		

TAIL LIFT IN-OP

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Air conditioning