

VEHICLE INSPECTION REPORT

PE24VMG

Peugeot Boxer 435 2.2 BlueHDi H2 140ps

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56483
Cap Code	PEBX2244PPHDTM2 4 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£11,400.00
Reg. date	05/03/2024	Colour	WHITE	CAP Average	£10,750.00
Year	2024	VIN	VF3YDBPFCPG059238	CAP Below	£9,475.00
Mileage	61,771 Miles Not Warranted	Body Style	Panel Van L4	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	04/03/2027	Gears	6

E/MIRRORS, AD/BLUE

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Rear parking sensor
- Front electric windows


Photos







Condition Check



Damage Photos



1: Door Mirror Glass os
Broken
Replace



2: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm




3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Panel Rear
Scratched
Over 25mm Not Thru Paint



6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Lamp nsr
Broken
Replace



8: Panel Rear
Scratched
Over 25mm Thru Paint



9: Door Mirror Glass ns
Broken
Replace

10: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
Sat nav	OK		Steering	OK	