

VEHICLE INSPECTION REPORT

FN21GYK

Daf CF 370

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 26/03/2021

Year 2021

Mileage 163,759 Km Not Warranted

Fuel Type DIESEL

GVW 32000kg

Colour GREEN

VIN XLRADM4100G313623

Body Style Hookloader

Service history None

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WANRING LIGHT ON DASH, SHEETING SYSTEM


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4





Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Panel Front
Cracked
Replace



3: Bumper Front
Dented
With Paint Damage

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door osf
Chipped
Multiple Chips

6: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				