

VEHICLE INSPECTION REPORT

GF66RYA

VOLVO FH 500

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Bedford	GVW	44000kg	Gearbox	AUTOMATIC
Reg. date	12/10/2016	Colour	WHITE	Axle Combi	6x2
Year	2016	VIN	YV2RT40C2HB791217	Steering Combi	Mid-Lift
Mileage	619,276 Km Not Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	Cab Type	GLOBETROTTER CAB		

SLIDING 5TH WHEEL

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Air conditioning

Photos



