

VEHICLE INSPECTION REPORT

BF68VBU

Iveco Daily 2.3

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38810
Cap Code	IVDA23S352VDTM2 4 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£3,925.00
Reg. date	12/11/2018	Colour	WHITE	CAP Average	£3,325.00
Year	2018	VIN	ZCFC1358405255448	CAP Below	£2,525.00
Mileage	85,708 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	6

COLLECTED AS NON RUNNER - ELECTRIC ISSUES, CUTS OUT INTERMITTENTLY 3520 WB

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Radio/CD
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Cracked
Replace



3: Bumper Front
Cracked
Over 25mm



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
Multiple Chips



9: Door nsr
Dented
Over 30mm



10: Door osr
Dented
Over 30mm



11: Qtr Panel osr
Dented
With Paint Damage



12: Qtr Panel osr
Dented
Over 30% Of Panel



13: Qtr Panel Moulding os
Broken
Replace



14: Seat Base Cover nsf
Soiled
Heavy



15: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		