

VEHICLE INSPECTION REPORT

PE65VCN

DAF LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location	Avonmouth	Colour	RED	Last service miles	718,383
Reg. date	01/12/2015	VIN	XLRAEL3700L449655	MOT Due	30/09/2026
Year	2015	Body Style	Box Van	Cab Type	DAY CAB
Mileage	718,400 Km Warranted	Service history	Full	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Axle Combi	4x2
GVW	18000kg	Last service date	11/09/2026	Rear Suspension	Steel

COLLECTED AS NON-RUNNER-CAB FLOOR, REAR AXLE, TAIL LIFT DECK ISSUES

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Bonnet
Chipped
Multiple Chips



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Door osf
Chipped
Multiple Chips



6: Door osf
Dented
With Paint Damage



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



9: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



10: Carpets Front
Broken
Replace



11: Seat Base Cover of
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Poor Average	Odour	Average
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		