

VEHICLE INSPECTION REPORT

YS21XMA

FORD TRANSIT 350 2.0 EcoBlue 130ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	45198
		Cap Code	FOTR20R11ATDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£14,750.00
Reg. date	08/03/2021	Colour	WHITE	CAP Average	£13,150.00
Year	2021	VIN	WF0AXXTTRALT45581	CAP Below	£10,750.00
Mileage	60,869 Miles Not Warranted	Body Style	Tipper	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	6


AD BLUE, TOW BAR





Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Front parking sensor
- Drivers airbag
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Door nsf
Chipped
Edge Chip



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Door osf
Chipped
Edge Chip



7: Door osf
Dented
Over 30mm



8: Qtr Panel osr
Dented
Over 30mm



9: Handle Outer osf
Scratched (Painted)
Over 25mm Not Thru Paint



10: Wing osf
Scratched
Over 25mm Not Thru Paint



11: Bumper Front
Scratched
Over 25mm Not Thru Paint



12: Seat Base Cover osf
Holed
Over 3mm



13: Centre Console Front
Broken
Replace



14: Glove Box Lid
Broken
Replace



15: Centre Console Front
Scuffed
Over 25mm



16: Seat Base Cover nsf
Holed
Over 3mm



17: Centre Console Front
Missing
Replace



18: Qtr Panel Arch Extension os
Broken
Replace

Interior

Carpet Condition Seat Condition

Average
Average

Upholstery Condition Odour

Average
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		
		Radio	OK

